View NSN Online: https://aerobasegroup.tw/nsn/6550-01-332-4770

BECTON-DICKINSON MICROBIOLOGY SYSTEMS INC -- GRAM IODINE SOLUTION,12297,12299 -- 6550-01-332-4770

============ Product Identification =========================

Product ID:GRAM IODINE SOLUTION,12297,12299

MSDS Date:01/21/1991

FSC:6550

NIIN:01-332-4770

Kit Part:Y

MSDS Number: BQSYP === Responsible Party ===

Company Name: BECTON-DICKINSON MICROBIOLOGY SYSTEMS INC

Address:250 SCHILLING CIR

Box:243

City:COCKEYSVILLE

State:MD ZIP: 21030

Country:US

Info Phone Num:301-771-0100/301-666-0100

Emergency Phone Num:301-584-7169 Preparer's Name:DALE M. OREM

CAGE:05545

=== Contractor Identification ===

Company Name: BECTON DICKINSON AND CO MICROBIOLOGY SYSTEMS DIV

Address:250 SCHILLING CIRCLE

Box:City:HUNT VALLEY

State:MD

ZIP:21030-1103 Country:US

Phone:410-771-0101

CAGE:05545


====== Composition/Information on Ingredients ========

Ingred Name:IODINE/POVIDINE-IODINE (IODINE-2-POLYVINYL-PYRROLIDIONE COMPLEX)

CAS:75

| 53-56-2 |
|---|
| RTECS #:NN1575000 |
| Fraction by Wt: 12.5% Other REC Limits:NONE RECOMMENDED |
| OSHA PEL:C 0.1 PPM |
| ACGIH TLV:C 0.1 PPM; 9293 |
| ====================================== |
| LD50 LC50 Mixture:LD50 (ORAL, RAT) NOT KNOWN |
| Routes of Entry: Inhalation:NO Skin:YES Ingestion:NO |
| Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO |
| Health Hazards Acute and Chronic:ACUTE- EYES: MAY CAUSE IRRITATION. SKIN: MAY CAUSE STAIN AND/OR IRRITATION. INHALATION:VAPORS MAY |
| IRRITATE RE |
| SPIRATORY TRACT. INGESTION:IODINE MAY CAUSE BURNING |
| SENSATION OR ABDOMINAL PAIN. CHRONIC-NO T KNOWN |
| Effects of Overexposure:EYE AND SKIN IRRITATION, ABDOMINAL PAIN |
| Medical Cond Aggravated by Exposure:NOT KNOWN |
| ====================================== |
| First Aid:CALL A DOCTOR IF SYMPTOMS PERSIST. EYE:IMMEDIATELY FLUSH WITH |
| WATER FOR 15 MINUTES, HOLDING EYELIDS OPEN. SKIN:WASH WITH SOAP & |
| WATER. INHALED:REMOVE TO FRESH AIR. ORAL:IF CONSCIOUS DRINK 3 |
| GLA SSES OF WATER. CALL A PHYSICIAN. |
| COLO CI WITTER. OTTE TOTO INTO |
| ====================================== |
| Flash Point:NOT DETERMINED |
| Extinguishing Media:PRODUCT IS NOT FLAMMABLE. USE MEDIA SUITABLE FOR SURROUNDING FIRE. |
| Fire Fighting Procedures:WEAR FIRE FIGHTING PROTECTIVE EQUIPMENT AND A |
| SELF CONTAINED BREATHING APPARATUS. COOL FIRE EXPOSED CONTAINERS |
| WITH WATER SPRAY. Unusual Fire/Explosion Hazard:NOT KNOWN |
| Chadaan no, Explosion nazaranto i mitottit |
| ======== Accidental Release Measures ========== |

Spill



====== Disposal Considerations ============

Waste Disposal Methods:WASTE MATERIAL CAN BE DISPOSED OF WITH NORMAL LAB TRASH. FOLLOW ALL LOCAL, STATE AND FEDERAL GUIDELINES.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability

for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.