## 

Address:3601 UNION RD Box:6

City:HOLLISTER

State:CA

ZIP:95024-0006

Country:US

Info Phone Num:408-637-3731

=== Responsible Party ===

**Emerge** 

ncy Phone Num:408-637-3731

Preparer's Name: CHARLES MARTIN

CAGE:03AF4

=== Contractor Identification ===

Company Name: TELEDYNE RYAN AERONAUTICAL

Company Name: TELEDYNE RYAN AERONAUTICAL

Address:3601 UNION RD

Box:6

City:HOLLISTER

State:CA

ZIP:95024-0006

Country:US

Phone: 408-637-3731

CAGE:03AF4

====== Composition/Information on Ingredients =======

Ingred Name: NON-HAZARDOUS INGREDIENTS

========= Hazards Identification ===========

Routes of Entry: Inhalation:YES Skin:YES Ingestion:NO

Reports of Ca

rcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:NITROGEN OXIDES-IRRITATION & BURNING. Explanation of Carcinogenicity:NONE Effects of Overexposure:NITROGEN OXIDES-IRRITATION, HEADACHE, DIZZINESS, FALL IN BLOOD PRESSURE, CONGESTION IN NOSE & THROAT.
======================================
First Aid:INHALATION: REMOVE TO FRESH AIR. OBTAIN MEDICAL ATTENTION IN ALL CASES.
======================================
Fire Fighting Procedures:DON'T FIGHT FIRE INVOLVING THIS UNIT. Unusual Fire/Explosion Hazard:THIS UNIT CONTAINS HIGH ENERGY MATERIALS.
======================================
Handling and Storage Precautions:HANDLE W/CARE AVOIDING ELECTROSTATIC DISCHARGE, HEAT & IMPACT. STORE IN DRY, MOISTURE FREE ENVIRONMENT Other Precautions:UNITS WHICH HAVE INCURRERD SUBSTANTIAL IMPACT MAY SUSTAIN INTERNAL DAMAGE. CONSULT W/TRA ENGINEERING STAFF FOR EVALUATION.
====== Exposure Controls/Personal Protection ========
Eye Protection:SAFETY GLASSES Supplemental Safety and Health NET EXPLOSIVE WEIGHT PER UNIT IS 0.13 GRAMS.
========= Physical/Chemical Properties =========
Appearance and Odor:METALLIC W/NO ODOR.
======== Stability and Reactivity Data =========
Stability Indicator/Materials to Avoid:YES Stability Condition to Avoid:ELECTROSTATIC DISCHARGE, HEAT & IMPACT. Hazardous Decomposition Product

s:METAL FRAGMENTS. BY-PRODUCTS OF COMBUSTION: CO2 & NITROGEN OXIDES.

======= Disposal Considerations ===========

Waste Disposal Methods:UNITS SHOULD BE DEACTIVATED BY A RCRA PERMITTED FACILITY IAW/FEDERAL, STATE & LOCAL REGULATIONS. EPA WASTE CODE D003. DETONATING FUSE UN0367.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of Americ a in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.