

GENERAL ELECTRIC CO GE LIGHTING -- F10LWX/ES,F10SP35/RS/WM,FLUORESCENT LAMP --
6210-01-190-8369

===== Product Identification =====

Product ID:F10LWX/ES,F10SP35/RS/WM,FLUORESCENT LAMP

MSDS Date:09/21/1994

FSC:6210

NIIN:01-190-8369

MSDS Number: CBTFV

=== Responsible Party ===

Company Name:GENERAL ELECTRIC CO GE LIGHTING

Address:NELA PARK NO 4310

City:CLEVELAND

State:OH

ZIP:44112

Country:US

Info Pho

ne Num:216-266-3349

Emergency Phone Num:216-266-3349

Preparer's Name:SEE SUPPLIMENTAL DATA

CAGE:08805

=== Contractor Identification ===

Company Name:GENERAL ELECTRIC CO GE LIGHTING

Address:NELA PARK NO 4705

Box:City:CLEVELAND

State:OH

ZIP:44112

Country:US

Phone:800-624-0624/216-266-2121

CAGE:08805

===== Composition/Information on Ingredients =====

Ingred Name:MERCURY (SARA 313) (CERCLA)

CAS:7439-97-6

RTECS #:OV4550000

Other REC Limits:NONE RECOMMENDED

OSHA PEL:C, 0.1 MG/M3; Z

-2
ACGIH TLV:S,0.025 MG/M3; A4;96
EPA Rpt Qty:1 LB
DOT Rpt Qty:1 LB

=====
Hazards Identification
=====

LD50 LC50 Mixture:TLV FOR MERCURY IS 0.025MG/M*3
Routes of Entry: Inhalation:NO Skin:NO Ingestion:NO
Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:**ARTICLE** SHOULD THE TUBE BREAK, A
WHITE POWDER WILL COME OUT.IT IS A HALOPHOSPHATE
POLYMER.FLUORESCENT TUBES CONTAIN MERCURY.MOST OF THE MERCURY WILL
BE ADSOR
BED ONTO THE POLYMER AS IT CONDENSES,BU T SOME MERCURY
VAPOR WILL BE RELEASED TO THE ATM.THIS BECOMES A PROBLEM WHEN A
LARGE NUMBER OF TUBES ARE BROKEN AT ONCE.
Explanation of Carcinogenicity:THERE ARE NO INGREDIENTS ABOVE 0.1%
WHICH ARE IDENTIFIED AS CARCINOGENS BY NTP,IARC OR OSHA.
Effects of Overexposure:NONE SPECIFIED BY MANUFACTURER.
Medical Cond Aggravated by Exposure:NONE SPECIFIED BY MANUFACTURER.

=====
First Aid Measures
=====

First Ai
d:SKIN/EYES:BE CAREFUL OF THE GLASS CHARDS.INHAL:REMOVE TO
FRESH AIR.GIVE OXYGEN OR ARTIFICIAL RESPIRATION IF NEEDED.GET
MEDICAL ASSTSTANCE IF NEEDED.INGEST:UNLIKE ROUTE OF EXPOSURE.

=====
Fire Fighting Measures
=====

Flash Point:NONE
Extinguishing Media:USE MEDIA APPROPRIATE FOR SURROUNDING FIRE.
Fire Fighting Procedures:USE A SELF-CONTAINED BREATHING APPARATUS AND
FULL PROTECTIVE EQUIPMENT.
Unusual Fire/Explosion Hazard:IF A LARGE AMOUNT OF TUBES
IS INVOLVED
THERE MAY BE A HAZARD FROM MERCURY VAPOR.

=====
Accidental Release Measures
=====

Spill Release Procedures:HMIS SUGGESTS USING PROPER PROTECTIVE
EQUIPMENT.NORMAL PICK UP PROCEDURES,HOWEVER,DISPOSAL VARIES FROM
STATE TO STATE.CONSULT YOUR ENVIRONMENTAL COORDINATOR.HMIS DOES NOT
BELIEVE THAT A MERCURY CLEAN UP KIT IS INDICATED FOR THIS
SITUATION.
Neutralizing Agent:NOT APPLICABLE.

=====
Handling and Storage
=====

=====

Handling and Storage Precautions:STORE IN A COOL,DRY,WELL-VENTILATED PLACE.

Other Precautions:AVOID PHYSICAL DAMAGE.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:NOT NEEDED IN NORMAL SERVICE.A NIOSH RESPIRATOR FOR MERCURY VAPOR OR A SCBA MAY BE NEEDED IN THE EVENT THAT A LARGE NUMBER OF TUBES ARE BROKEN AT ONCE.

Ventilation:NO SPECIAL REQUIREMENTS.

Protective Gloves:NOT NEEDED IN NORMAL SERVICE.

Eye Protection:NOT NEEDED IN NORMAL SERVICE.

Other Protective Equipment:PROTECTIVE GLOVES AND SAFETY GOGLES SHOULD BE USED WHEN CLEANING UP BROKEN TUBES.

Work Hygienic Practices:USE REASONABLE CARE IN HANDLING THIS PRODUCT.

Supplemental Safety and Health

THIS MSDS REFLECTS THE CONTENTS OF A LETTER FROM A.M.

ZIELINSKI,LIGHTING ENVIRONMENTAL,HEALTH AND SAFETY DEPT OF GE,DATED 21SEP94, AND A TELEPHONE CONVERSATION WITH HIM ON 22OCT96.

===== Physical/Chemical Properties =====

HCC:N1

Solubility in Water:INSOLUBLE

Appearance and Odor:FLUORESCENT TUBE 4FT X 1-1/2 INCHES(DIAM)

===== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES
NONE SPECIFIED BY MANUFACTURER.

Stability Condition to Avoid:PHYSICAL DAMAGE.

Hazardous Decomposition Products:MERCURY VAPOR IF LAMP IS BROKEN.

===== Disposal Considerations =====

Waste Disposal Methods:DISPOSE OF IN ACCORDANCE WITH FEDERAL,STATE AND LOCAL

REGULATIONS.A QUESTION OF WHETHER LARGE NUMBERS OF
FLUORESCENT TUBES ARE CONSIDERED HAZARDOUS WASTE BECAUSE THEY
CONTAIN MERCURY;CONTACT YOUR ENVI RONMENTAL COORDINATOR.

Disclaimer (provided with this information by the compiling agencies):
This information is formulated for use by elements of the Department
of Defense. The United States of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any
person utilizing this
document should seek competent professional advice to verify and
assume responsibility for the suitability of this information to their
particular situation.