

OEA AEROSPACE INC. -- 51325-3 TRANSFER CONNECTOR -- 1377-01-241-7982

=====
Product Identification
=====

Product ID:51325-3 TRANSFER CONNECTOR

MSDS Date:01/12/1996

FSC:1377

NIIN:01-241-7982

MSDS Number: CCGLS

=== Responsible Party ===

Company Name:OEA AEROSPACE INC.

Address:HWY 12 AND ET RD

Box:KK

City:FAIRFIELD

State:CA

ZIP:94533-0659

Country:US

Info Phone Num:707-422-1880

Emergency Phone Num:707-

422-1880

Preparer's Name:S SCHOOLFIELD/J KOHRING

CAGE:17610

=== Contractor Identification ===

Company Name:OEA AEROSPACE INC

Address:3530 BRANSCOMBE RD

Box:KK

City:FAIRFIELD

State:CA

ZIP:94533-0659

Country:US

Phone:707-422-1880

CAGE:17610

=====
Composition/Information on Ingredients
=====

Ingred Name:HEXANITROSTILBENE I

Ingred Name:HEXANITROSTILBENE II

=====
Hazards Identification
=====

Routes of Entry: Inhalation:NO Skin:NO Ingestion:YES

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO
Health Hazards Acute and Chronic:HEXANITROTILBENE I & II IS POSITIVE
BIOLOGICAL ACTIVITY IN THE AMES MUTAGENICITY TEST. INHALATION:
IRRITATION TO NOSE, THROAT, MUCOUS MEMBRANES, NAUSEA & ALLERGIC
REACTIONS. SKIN: IRRITATION, ALLERGIC REACTIONS. EYES: IRRITATION.
INGESTION: TOXIC.

Explanation of Carcinogenicity:NONE

Effects of Overexposure:IRRITATION, NAUSEA, REDNESS.

=====
===== First Aid Measures =====
=====

First Aid:EYES: FLUSH W/WATER FOR 15 MINS. SKIN: WASH W/SOAP & WATER.
INHALATION: REMOVE TO FRESH AIR. OBTAIN MEDICAL ATTENTION IN ALL
CASES.

=====
===== Fire Fighting Measures =====

Extinguishing Media:DON'T ATTEMPT TO EXTINGUISH.
Fire Fighting Procedures:EVACUATE AREA. USE SCBA W/FULL FACE.
Unusual Fire/Explosion Hazard:IF EXPOSED TO FIRE, UNIT MAY
ACTUATE/EXPLODE.

=====
===== Accidental Release Measures =====

Spill
Release Procedures:CALL LOCAL HAZARDOUS MATERIALS TEAM. REMOVE
IGNITION SOURCES. COVER/EXPOSE MATERIAL W/VEGETABLE OIL & REMOVE
FOR APPROVED DISPOSAL. USE FLAME RETARDANT CLOTHING, SAFETY GLASSES
& NON-SPARKING TOOLS.

=====
===== Handling and Storage =====

Handling and Storage Precautions:DON'T STORE AT TEMP >200F. ANTI-STATIC
BAGS SHALL BE USED FOR STORAGE & SHIPPING.

=====
===== Exposure Controls/Personal Protection =====

Respiratory

Protection:WEAR NIOSH APPROVED HEPA RESPIRATOR IF PEL/TLV ARE EXCEEDED.

Ventilation:LOCAL EXHAUST: REQUIRED FOR TEST FIRING.

Protective Gloves:POLY-BENZ-IMMIEAZOLE

Eye Protection:SAFETY GLASSES

Other Protective Equipment:FLAME RETARDANT COAT & GROUNDING STRAPS TO PREVENT ELECTROSTATIC DISCHARGE.

Supplemental Safety and Health

===== Physical/Chemical Properties =====

Solubility in Water:LOW/SLIGHT

Appearance and Odor:YELLOW POWDER W/NO ODOR.

=====

== Stability and Reactivity Data =====

Stability Indicator/Materials to Avoid:YES

ALKALIS, COPPER, BRONZE, CORROSIVES & OXIDIZERS.

Stability Condition to Avoid:MECHANICAL SHOCK, STATIC ELECTRICITY, HEAT, FLAME/SPARKS.

Hazardous Decomposition Products:CO, NITROGEN, NITROUS OXIDES, HYDROGEN, CARBON, CO2, WATER.

===== Disposal Considerations =====

Waste Disposal Methods:DISPOSE OF IAW/FEDERAL, STATE & LOCAL REGULATIONS. UNFIRED UNITS/WASTE, DISPOSE AS REACTIVE HAZARDOUS WASTE, D003.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.