View NSN Online: https://aerobasegroup.tw/nsn/6830-00-138-2482

E I DU PONT DE NEMOURS & CO FREON PRODUCTS DIV -- FREON 502 -- 6830-00-138-2482

Product ID:FREON 502 MSDS Date:10/01/1985 FSC:6830 NIIN:00-138-2482 MSDS Number: BDBJB === Responsible Party === Company Name: E I DU PONT DE NEMOURS & CO FREON PRODUCTS DIV Address: FREON PRODUCTS DIVISION City:WILMINGTON State:DE ZIP:19898 Info Phone Num:302-774-2421 **Emergency Phone N** um:302-774-2421 Preparer's Name: T.D.ARMSTRONG CAGE:B0589 === Contractor Identification === Company Name: DU PONT E I DE NEMOURS AND CO INC PETROCHEMICALS DEPT Address:1251 BRANDYWINE BLDG Box:City:WILMINGTON State:DE ZIP:19898 Phone:302-773-5676 CAGE:73925 Company Name: EI DU PONT DE NEMOURS & CO Address: RAKETSTRAAT, 100, RUE DE LA FUSEE City:BRUSSEL Country:BE Phone:32-(0)15-401.505 CAGE:B0589 Company Name:NATIONAL REFRIGERANTS INC Address:11401 ROOSEVELT BLVD Box:City:PHILADELPHIA State:PA Ζ

IP:19154 Country:US Phone:215-834-0200 CAGE:7Y146

Ingred Name:CHLOROPENTAFLUOROETHANE (SARA III) CAS:76-15-3 RTECS #:KH7877500 Fraction by Wt: 51.2% OSHA PEL:1000 PPM ACGIH TLV:1000 PPM; 9192 Ozone Depleting Chemical:1

Ingred Name:CHLORODIFLUOROMETHANE CAS:75-45-6 RTECS #:PA6390000 Fraction by Wt: 48.8% OSHA PEL:1000 PPM ACGIH TLV:1000PPM; 9192 Ozone Depleting Chemical:2

================== Hazards Identification ======

LD50 LC50 Mixture:300,000 PPM/2 HR(FC-22; LC50=RAT) Routes of Entry: Inhalation:YES Skin:NO Ingestion:NO Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO Health Hazards Acute and Chronic:INHALATION: CAN CAUSE SUFFOCATION BY REDUCING OXYGEN. MAY LEAD TO NARCOSIS, CARDIAC IRREGULARITIES, UNCONSCIOUSNESS OR DEATH. SKIN AND EYE CONTACT MAY CAUSE FROSTBITE. Effects of Overexposure:BREATHING HIGH CONCENTRATIONS OF VAPOR MA CAUSE LIGHT-HEADEDNESS, GIDDINESS, SHORTNES S OF BREATH AND MAY LEAD TO

NARCOSI CARDIAC IRREGULARITIES, UNCONSCIOUSNESS OR DEATH. Medical Cond Aggravated by Exposure:CARDIOVASCULAR DISEASE

First Aid:INHALATION: REMOVE TO FRESH AIR, CALL A PHYSICIAN. IF NOT BREATHING, GIVE ARTIFICIAL RESPIRATION, PREFERRABLY MOUTH-TO-MOUTH. IF BREATHING IS DIFFICULT, GIVE OXYGEN. DO NOT GIVE EPINEPHRIN OR SIMILAR DRUGS. EYE: FLUSH WITH WATER, CALL A PHYSICIAN IF FRO STBITE OCCURS.SKIN: FLUSH WITH WATER. TREAT FOR FROSTBITE IF NECESSARY.

Flash Point Method: TOC
Flash Point:NONE Lower Limits:NONFLAMMABLE
Upper Limits:NONFLAMMABLE
Extinguishing Media:NONFLAMMABLE
Fire Fighting Procedures:SELF-CONTAINED BREATHING APPARATUS MAY BE REQUIRED IF CYLINDERS RUPTURE OR RELEASE UNDER FIRE CONDITIONS. Unusual Fire/Explosion Hazard:CYLINDERS ARE EQUIPPED WITH TEMPERATURE A PRESSURE RELIEF D
EVICES BUT STILL MAY RUPTURE UNDER FIRE
CONDITIONS.DECOMPOSITION MAY OCCUR.
======================================
Spill Release Procedures: VENT AREA, ESPECIALLY LOW PLACES WHERE HEAVY VAPORS MIGHT COLLECT. REMOVE OPEN FLAMES. Neutralizing Agent: NONE
======================================
Handling and Storage Precautions:STORE CNTNR IN CLEAN, DRY AREA. DO NOT HEAT ABOVE 125F.
Other Precautions:NOTE TO PHYSICIANS: BECAUSE O F A POSSIBLE INCREASED
RISK O ELICITING CARDIAC DYSRYTHMIAS, CATECHOLAMINE DRUGS, SUCH AS EPINEPHRINE, SHOUL BE CONSIDERED ONLY AS A LAST RESORT IN LIFE THREATENING EMERGE NCIES.
======== Exposure Controls/Personal Protection ====================================
Respiratory Protection: USE NIOSH/MSHA APPROVED SCBA IN CASE OF SPILL OR RELEASE.

Ventilation:NORMAL VENTILATION FOR STANDARD MANUFACTURING PROCEDURES IS GENERALLY ADEQUATE. LOCAL EXHAUST FOR RELEASE OF LARGE AMTS. Protective Gloves :LINED NEOPRENE Eye Protection:CHEM SPLASH GOGGLES Other Protective Equipment:FULL WORK CLOTHING TO PREVENT REPEATED OR PROLONG CONTACT. Work Hygienic Practices:AVOID BREATHING VAPORS AND LIQUID CONTACT WITH SKIN. Supplemental Safety and Health USE IN WELL VENTILATED AREA.

HCC:G3 Boiling Pt:B.P. Text:-50F,-45.5C Vapor Pres:8016 Vapor Density:4.2 Spec Gravity:1.242 Appearance and Odor:CLEAR, COLORLESS LIQUEFIED GAS. SL IGHT ETHEREAL ODOR Percent Volatiles by Volume:100

Stability Indicator/Materials to Avoid:YES ALKALI OR ALKALINE EARTH METALS- POWDERED AL, ZN, BE, ETC Stability Condition to Avoid:AVOID OPEN FLAME AND HIGH TEMPERATURES. Hazardous Decomposition Products:CAN BE DECOMPOSED BY HIGH TEMPERATURES (OPE FLAMES, GLOWING METAL SURFACES, ETC.) FORMING HYDROCHLORIC & FLUORIC ACIDS.

====== Disposal Consideratio

Waste Disposal Methods:COMPLY WITH FEDERAL,STATE AND LOCAL REGULATIONS OR REMOVE TO PERMITTED WASTE DISPOSAL FACILITY. RECLAIM BY DISTILLATION.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any

person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.