

3M COMPANY-ADHESIVES,COATINGS & SEALERS DIV -- SCOTCHWELD 2216A ADHESIVE (GRAY) --
8040-00-152-0019

===== Product Identification =====

Product ID:SCOTCHWELD 2216A ADHESIVE (GRAY)

MSDS Date:01/01/1987

FSC:8040

NIIN:00-152-0019

Kit Part:Y

MSDS Number: BDCTB

=== Responsible Party ===

Company Name:3M COMPANY-ADHESIVES,COATINGS & SEALERS DIV

Emergency Phone Num:612-733-1110 (OP55)

CAGE:04963

=== Contr

actor Identification ===

Company Name:3M MINNESOTA MINING AND MFG CO ADHESIVES SEALERS DIV

Address:3M CTR

Box:City:SAINT PAUL

State:MN

ZIP:55144-1000

Country:US

Phone:800-364-3577/651-737-6501(24 HOURS)

CAGE:04963

===== Composition/Information on Ingredients =====

Ingred Name:ALIPHATIC AMINE

Fraction by Wt: 61.0%

Ingred Name:ALUMINUM SILICATE PIGMENT (CLAY)

Fraction by Wt: 39.0%

Ingred Name:CARBON BLACK

CAS:1333-86-4

RTECS #:FF5800000

Fraction by Wt: 1.00%

OSHA PEL:3.5 MG/M

=====
Hazards Identification
=====

Effects of Overexposure:EYE:EXTR IRRT MAY CAUSE PERM EYE
DAMAGE.SKN:IRR&SENS.INHL:IRR.TINGES:IRR GI TRACT.

=====
First Aid Measures
=====

First Aid:EYE: FLUSH COPIOUSLY WATER 10 MIN. SKIN: THOROUGH WASH SOAP &
WATER. INH: REMOVE TO FRESH AIR. INGES: DRINK TWO GLASSES MILK OR
WATER. CALL PHYSICIAN.

=====
Fire Fighting Measures
=====

Extinguishing Media:CO2,FOAM,DRY CHEMICAL, WATER
Fire Fighting Procedures:WEAR SELF-CNTND BRTHG APP
Unusual Fire/Explosion Hazard:NONE

=====
Accidental Release Measures
=====

Spill Release Procedures:VENTILATE AREA, COLLECT SPILLED MATERIAL.
CLEANUP RESIDUE, PLACE IN APPROVED METAL CONTAINER.

=====
Handling and Storage
=====

Handling and Storage Precautions:AVOID CONTACT WITH EYE & SKIN. AVOID
INHL
OR EYE CONTACT WITH DUST FROM GRINDING OPERATIONS. WASH
CONTAMINATED CLOTHING BEFORE REUSE.
Other Precautions:VENT CURING OVENS TO OUTDOORS. KEEP CONTAINERS
CLOSED.

=====
Exposure Controls/Personal Protection
=====

Respiratory Protection:NONE
Ventilation:MECH(GEN)OR LOCAL EXHAUST THAT PROVIDES ADEQUATE
VENTILATION
Protective Gloves:IMPERVIOUS
Eye Protection:SAFETY GLASSES
Other Protective Equipment:SCBA IN FIRE. USE DUST MASK WHEN GRINDING
CURED RESIN.
Supplem

ental Safety and Health

PART A OF TWO PART KIT. BASIS: MSDS DTD INOV85(OSHA HAZCOMSTD), 3M
DOCUMENT 1031749 3M GENERIC P/N IS 62-2217-XXXX-X. KIT ALSO KNOWN
AS 22116B/A 3M EC2216B/A(GRAY;KEY1:N1

===== Physical/Chemical Properties =====

HCC:N1

Spec Gravity:1.26

Viscosity:52000 CP

Solubility in Water:INSOLUBLE

Appearance and Odor:GRAY PASTE

Percent Volatiles by Volume:0

===== Stability and Reactivity Data =====

Stability Indicator/M

aterials to Avoid:YES

Hazardous Decomposition Products:CO, CO2, N, SMOKE PARTICLES ON
EXPOSURE EXCESS HEAT OR FLAME

===== Disposal Considerations =====

Waste Disposal Methods:OBSERVE ALL APPLICABLE REGS BEFORE DISPOSAL.
CURED RESIN (A&B): DISPOSE IN SAN LANDFILL. SPILL: DISPOSE OF
CLEANUP MATERIAL BY INCINERATION.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Depart
ment

of Defense. The United States of America in no manner whatsoever,
expressly or implied, warrants this information to be accurate and
disclaims all liability for its use. Any person utilizing this
document should seek competent professional advice to verify and
assume responsibility for the suitability of this information to their
particular situation.