View NSN Online: https://aerobasegroup.tw/nsn/8030-00-174-3199

Product ID:SCOTCH-SEAL(TM)BRAND IND SEALANT 801 MSDS Date:06/30/1987 FSC:8030 NIIN:00-174-3199 **MSDS Number: BDFNS** === Responsible Party === **Company Name:3M GENERAL OFFICES** Address:3M CENTER **City:SAINT PAUL** State:MN ZIP:55144-1000 Country:US Info Phone Num:612-733-1110 **Emergency Phone N** um:612-733-1110 CAGE:04963 === Contractor Identification === Company Name: 3M MINNESOTA MINING AND MFG CO ADHESIVES SEALERS DIV Address:3M CTR Box:City:SAINT PAUL State:MN ZIP:55144-1000 Country:US Phone:800-364-3577/651-737-6501(24 HOURS) CAGE:04963 Ingred Name: POLYSULFIDE RUBBER Fraction by Wt: Other REC Limits: OSHA PEL: ACGIH TLV:

Ingred Name:PHENOLIC RESIN Fraction by Wt: Other REC Limits: OSHA PEL: ACGIH TLV:

Ingred

Name:SILICA, AMORPHOUS, DUST CAS:112945-52-5 RTECS #:VV7310000 Fraction by Wt: Other REC Limits:20 MPPCF OSHA PEL:6 MG/M3 ACGIH TLV:10 MG/M3; 8990

Ingred Name:CARBON BLACK CAS:333-86-4 RTECS #:FF5800001 Fraction by Wt: Other REC Limits:3.5 MG/CUM OSHA PEL:3.5 MG/CUM ACGIH TLV:3.5 MG/CUM

Ingred Name:MAGNESIUM ACETATE CAS:142-72-3 RTECS #:AI5600000 Fraction by Wt: Other REC Limits: OSHA PEL: ACGIH TLV:

Ingred Name:PETROLEUM DISTILLATE Fraction by Wt: 3.0% Other REC Limits: OSHA PEL: ACGIH TL V:

Effects of Overexposure:EYE:IRRITATION. SKIN: IRRITATION CONTACT W/ SKIN WILL CAUSE EXTREME DIFFICULTY IN CLEAN UP. USE OF ABRASIVES OR SOLVENTS FOR CLEANUP COULD CAUSE SKIN DAMAGE. INHAL:NO HAZARD.VAPOR OVEREXPOSURE:RESP IR RITATION LIGHT-HEADEDNESS. SYMPTOMS HEADACHE,WEAKNESS,FATIGUE OR UNCONSCIOUSNESS. INGEST, DIGESTIVE SYSTEM IRRITATION.

First Aid:EYE: FLUSH W/ LG AMTS OF H*20 FOR AT LEAST 15 MIN CALL PHYS. SKIN:WASH THOROUGHLY W/ SOAP + H*20 INHAL:REMOVE INDIVIDUAL TO FRESH AIR. CALL PHYSICIAN.INGEST:DO NOT INDUCE VOMITING.DRINK TWO GLA SSES OF MILK OR H*20.CALL PHYSICIAN.
======================================
Flash Point:7100F-37.78C Extinguishing Media:CO2,FOAM,DRY CHEM. Fire Fighting Procedures:FIRE FIGHTERS SHOULD BE EQUIPPED W/ SCBA.
======================================
Spill Release Procedures:CONTAIN SPILL.CLEAN UP RESIDUE + AREA OF SPILL.PLACE RESIDUE IN CONTAINER.
======================================
 Handling and Storage Precautions: KEEP AWAY FROM HEAT, SPARKS AND OPEN FLAME. USE ONLY WITH ADEQUATE VENTILATION TO REMOVE AND PREVENT VAPOR BUILD UP. KEEP CONTAINER CLOSED. Other Precautions: AVOID PROLONG BREATHING OF VAPORS AND PROLONGED OR REPEATED SKIN CONTACT.
======================================
Respiratory Protection:NIOSH/MSHA APPROVED RESP DEVICE IN ACCORD WITH EXPOSURE OF CONCERN Ventilation:USE ONLY IN AREAS W/ ENOUGH AIR MOVEMENT TO PREVENT VAPOR BUILD UP. Protective Gloves:IMPERVIOUS Eye Protection:CHEM GOGGLES Supplemental Safety and Health PART A OF A TWO PART KIT.KEY1:J1.
======================================

HCC:F4 Spec Gravity:1.36 Solubility in Water:LOW Appearance and Odor:BLACK Stability Indicator/Materials to Avoid:YES Hazardous Decomposition Products:CO,CO2,SULFUR COMPOUND

Waste Disposal Methods:MAY BE DISPOSED OF IN A SANITARY LANDFILL ACCORDING TO LOCAL + CURRENT U.S.ENVIRONMENTAL PROTECTION AGENCY REGULATIONS.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.