View NSN Online: https://aerobasegroup.tw/nsn/5910-00-868-3754

Product ID:85596 MSDS Date:01/01/1985 FSC:5910 NIIN:00-868-3754 MSDS Number: BFTGV === Responsible Party === Company Name:TECUMSEH PRODUCTS CO Address:S OTTAWA ST City:TECUMSEH State:MI ZIP:49286 Country:US Emergency Phone Num:5174238411 CAGE:59431
=== Contractor Identification === Company Name:TECUMSEH PRODUCTS C
O Address:S OTTAWA ST Box:City:TECUMSEH State:MI ZIP:49286 Country:US CAGE:59431
========= Composition/Information on Ingredients ====================================
Ingred Name:POLYCHLORINATED BIPHENYLS (PCBS) (SARA III) CAS:1336-36-3 RTECS #:TQ1350000 EPA Rpt Qty:1 LB DOT Rpt Qty:1 LB
======================================

Effects of Overexposure:ABSORBED THRU SKIN,LUNGS,INTESTINE.CAUSES CANCER,LIVER,KIDNEY,STOMACH,EYE,HEARING DISORDER(SUP DATA)

First Aid:EYES:FLUSH W/WATER IMMEDIATELY.SKIN:WASH W/SOAP IMMEDIATELY.INHAL:REMOVE TO FRESH AIR,GIVE ART.RESPIR.AS NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE QTY OF SALT WATER,INDUCE VOMITING,BUT DO NOT MAKE UNC ONSCIOUS PERSON VOMIT.
======================================
Spill Release Procedures: USE ABSORBENT & DIKES TO PREVENT RUNOFF. ISOLATE & NOTIFY PROPER AUTHORITIES.
======================================
and Storage ====================================
Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENTS. Other Precautions:LARGE CAPACITORS OF 3 LB OR MORE PCB REQUIRE LABELS IN STORAGE,USE & TRANSPORTATION
======================================
Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOOD Ventilation:LOCAL EXHAUST Protective Gloves:RUBBER-IMPERV Eye Protection:GOGGLES,FACE SHIELD Other Protective Equipment:FULL CLOTHING TO PREVENT S KIN CONTACT Supplemental Safety and Health OVEREXPOS:CAN CAUSE FORMATION OF CYSTS,CAUSES STILLBIRTHS.IRRITATES EYES,NOSE THROAT.
======================================
HCC:Z3 Appearance and Odor:LIGHT STRAW-COLORED LIQUID,AROMATIC ODOR
======================================
STRONG OXIDIZERS
======================================

Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED-GENERALLY HIGH

TEMPERATURE INCINERATION.ONLY APPROVED DISPOSAL OPERATOR PERMITTED.

Disclaimer (provided with this information by the compiling agencies): This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing this document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.