

ACTIVE & PASSIVE COMPONENTS -- SP207 -- 5915-00-964-3683

===== Product Identification =====

Product ID:SP207
MSDS Date:01/01/1985
FSC:5915
NIIN:00-964-3683
MSDS Number: BFZMB
=== Responsible Party ===
Company Name:ACTIVE & PASSIVE COMPONENTS
Address:148 SWEET HOLLOW RD
City:OLD BETHPAGE
State:NJ
ZIP:11804-1315
Country:US
Emergency Phone Num:800
CAGE:LO509

=== Contractor Identification ===

Company
Name:ACTIVE & PASSIVE COMPONENTS INC.
Address:148 SWEET HOLLOW RD
Box:City:OLD BETHPAGE
State:NJ
ZIP:11804-1315
Country:US
CAGE:LO509
Company Name:ACTIVE AND PASSIVE COMPONENTS INC
Address:148 SWEET HOLLOW RD
Box:City:OLD BETHPAGE
State:NJ
ZIP:11804-1315
Country:US
CAGE:50369

===== Composition/Information on Ingredients =====

Ingred Name:POLYCHLORINATED BIPHENYLS (PCBS) (SARA III)
CAS:1336-36-3
RTECS #:TQ1350000
EPA Rpt Qty:1 LB
DOT Rpt Qty:1 LB

===== Hazar

ds Identification =====

Effects of Overexposure:ABSORBED THRU SKIN,LUNGS,INTESTINE.CAUSES
CANCER,LIVER,KIDNEY,STOMACH,EYE,HEARING DISORDER(SUP DATA)

===== First Aid Measures =====

First Aid:EYES:FLUSH W/WATER IMMEDIATELY.SKIN:WASH W/SOAP
IMMEDIATELY.INHAL:REMOVE TO FRESH AIR,GIVE ART.RESPIR.AS
NEEDED.INGEST:GET MEDICAL ATTN.GIVE LARGE QTY OF SALT WATER,INDUCE
VOMITING,BUT DO NOT MAKE UNC ONSCIOUS PERSON VOMIT.

=====

===== Accidental Release Measures =====

Spill Release Procedures:USE ABSORBENT & DIKES TO PREVENT
RUNOFF.ISOLATE & NOTIFY PROPER AUTHORITIES.

===== Handling and Storage =====

Handling and Storage Precautions:STORAGE MUST FOLLOW RCRA REQUIREMENTS.

===== Exposure Controls/Personal Protection =====

Respiratory Protection:SUPPLIED AIR W/FULL FACEPIECE,HELMET OR HOOD

Ventilation:LOCAL EXHAUST

Protective Gloves:RUBBER-IMPER

V

Eye Protection:GOGGLES,FACE SHIELD

Other Protective Equipment:FULL CLOTHING TO PREVENT SKIN CONTACT

Supplemental Safety and Health

OVEREXPOS:CAN CAUSE FORMATION OF CYSTS,CAUSES STILLBIRTHS.IRRITATES
EYES,NOSE THROAT.

===== Physical/Chemical Properties =====

HCC:Z3

Appearance and Odor:LIGHT STRAW-COLORED LIQUID,AROMATIC ODOR

===== Stability and Reactivity Data =====

STRONG OXIDIZERS

===== Disposal Considerations =====

=====

Waste Disposal Methods:CONTROLLED DISPOSAL REQUIRED-GENERALLY HIGH
TEMPERATURE INCINERATION.ONLY APPROVED DISPOSAL OPERATOR PERMITTED.

Disclaimer (provided with this information by the compiling agencies):

This information is formulated for use by elements of the Department of Defense. The United States of America in no manner whatsoever, expressly or implied, warrants this information to be accurate and disclaims all liability for its use. Any person utilizing thi

s

document should seek competent professional advice to verify and assume responsibility for the suitability of this information to their particular situation.