

FISKE BROTHERS REFINING CO -- LUBRIPLATE, 105 -- 9150-00-076-1584

=====
Product Identification
=====

Product ID:LUBRIPLATE, 105

MSDS Date:01/01/1994

FSC:9150

NIIN:00-076-1584

MSDS Number: CDVDR

=== Responsible Party ===

Company Name:FISKE BROTHERS REFINING CO

Address:1500 OAKDALE AVE

City:TOLEDO

State:OH

ZIP:43605

Country:US

Info Phone Num:419-691-2491

Emergency Phone Num:800-255-3924

Preparer's

Name:JAMES R KONTAK

CAGE:9N579

=== Contractor Identification ===

Company Name:FISKE BROS REFINING CO

Address:129 LOCKWOOD ST

Box:City:NEWARK

State:NJ

ZIP:07105-4720

Country:US

Phone:201-589-9150

CAGE:73219

Company Name:FISKE BROTHERS REFINING CO

Address:1500 OAKDALE AVE

Box:City:TOLEDO

State:OH

ZIP:43605

Country:US

Phone:419-691-2491

CAGE:9N579

=====
Composition/Information on Ingredients
=====

Ingred Name:NON-HAZARDOUS INGREDIENTS

OSHA PEL:N/K

ACGIH TLV:N/K

=====

=====
Hazards Identification
=====

LD50 LC50 Mixture:NONE SPECIFIED BY MANUFACTURER.

Routes of Entry: Inhalation:YES Skin:YES Ingestion:YES

Reports of Carcinogenicity:NTP:NO IARC:NO OSHA:NO

Health Hazards Acute and Chronic:ACUTE:PROLONGED OR REPEATED SKIN CONTACT MAY CAUSE IRRITATION. PRODUCT CONTACTING EYES MAY CAUSE IRRITATION. HUMAN HEALTH RISKS VARY FROM PERSON TO PERSON. AS PRECAUTION, EXPOSURE TO LIQUIDS, VAPORS, MISTS & FUMES SHOULD BE MINIMIZED.

THIS PRODUCT HAS LOW ORDER OF ACUTE ORAL TOXICITY, BUT MINUTE AMTS (EFTS OF OVEREXP)

Explanation of Carcinogenicity:NOT RELEVANT.

Effects of Overexposure:HLTH HAZ:ASPIRATED INTO THE LUNGS DURING INGESTION MAY CAUSE MILD TO SEVERE PULMONARY INJURY.

Medical Cond Aggravated by Exposure:NONE SPECIFIED BY MANUFACTURER.

=====
First Aid Measures
=====

First Aid:EYE:FLUSH W/CLEAR WATER FOR @ LST 15 MINS OR UNTIL IRRITATION SUBSIDES. IF IRRIT PERSISTS,

CONSULT PHYS. SKIN:REMOVE ANY CONTAMD

CLTHG & WASH W/SOAP & WARM WATER. IF INJECTED BY HIGH PRESS UNDER SKIN, REGARDLESS OF APPEARANCE OR ITS SIZE, CONT PHYS IMMED. DELAY MAY CAUSE LOSS OF AFFECTED PART OF BODY. INHAL:VAP PRESS IS VERY LOW & INHAL @ ROOM TEMP IS NOT PROBLEM. IF OVERCOME BY VAPOR FROM(SUPDAT)

=====
Fire Fighting Measures
=====

Flash Point Method:COC

Flash Point:360F,182C

Lower Limits:0.9%

Upper Limits:7.0%

Extinguishing Med

ia:FOAM, DRY CHEMICAL, CARBON DIOXIDE OR WATER SPRAY(FOG).

Fire Fighting Procedures:USE NIOSH APPROVED SCBA & FULL PROTECTIVE EQUIPMENT . COOL EXPOSED CONTAINERS WITH WATER.

Unusual Fire/Explosion Hazard:DO NOT STORE OR MIX WITH STRONG OXIDANTS. EMPTY CONTAINERS RETAIN RESIDUE. DO NOT CUT, DRILL, GRIND, OR WELD, AS THEY MAY EXPLODE.

=====
Accidental Release Measures
=====

Spill Release Procedures:SCRAPE UP GREASE, WASH REMAINDER WITH SUITABLE PET

